



579

581

50'+/-

50'+/-

Property owner has trimmed his trees to open sight distance to the south.


CCAD



CR 581 at CR 549 visibility

Trim and/or remove trees outside and inside of fence to improve visibility. Increased traffic due to construction at SH 160 and SH 121

On CR 581 looking N. on CR 579




CR 579

CR 581

06.15.2017

On CR 581 looking S. on CR 579. This property owner has trimmed his trees on his own.




Trim and/or remove trees outside and inside of fence to improve visibility. Increased traffic due to construction at SH 160 and SH 121


On CR 581 looking N. on CR 579

CR 579

CR 581


06.15.2017





On CR 581 looking S. on CR 579. This property owner has trimmed his trees on his own.

06.15.2017



On CR 581 looking
N. on CR 579

CR 579

Trim and/or remove trees outside
and inside of fence to improve
visibility. Increased traffic due to
construction at SH 160 and SH 121

CR 581

06.15.2017

On CR 581 looking S. on CR 579. This property owner has trimmed his trees on his own.

