



Ratcliff Constructors, LP 4200 Beltway Drive Addison, Texas 75001 Phone: (972) 432-9969 Fax: (972) 432-9943

Project: 21-501 - Collin County Adult Detention Facility, Phase 1 Addition 4300 Community Avenue McKinney, Texas 75071

Prime Contract Potential Change Order #098: Boiler Regulators & Solenoid

Collin County

4600 Community Avenue

McKinney Texas, 75071

PCO NUMBER/REVISION:

098/0

CONTRACT:

FROM:

Ratcliff Constructors, LP 4200 Beltway Drive Addison Texas, 75001

1 - Collin County Adult Detention Facility, Phase 1 Addition Prime Contract

REQUEST RECEIVED FROM:

STATUS:

Pending - In Review

CREATED BY:

CJ Perry (Ratcliff Constructors, LP)

CREATED DATE:

4/4 /2024

REFERENCE:

PRIME CONTRACT CHANGE ORDER:

FIELD CHANGE:

SCHEDULE IMPACT:

No

LOCATION:

Amount Based

ACCOUNTING METHOD:

No

PAID IN FULL: TOTAL AMOUNT:

\$4,719.16

POTENTIAL CHANGE ORDER TITLE: Boiler Regulators & Solenoid

CHANGE REASON: Allowance

POTENTIAL CHANGE ORDER DESCRIPTION: (The Contract Is Changed As Follows)

Boiler Regulators

Provide for additional materials, labor, and equipment required to add regulators and a solenoid to the boilers. Existing regulator for gas boilers to be removed and transmitted to Collin County. Power for the solenoid shall be connected to LC-59 per Engineer. See backup.

ATTACHMENTS:

#	Cost Code	Description	Туре	Amount		
1	22-101 - Plumbing Alt.	Boiler Regualtors	Subcontractor	\$ 4,237.19		
2		Ratcliff Bonds (1.25%)		\$ 52.96		
3		Ratcliff Fee (10.00%)		\$ 429.01		
·						
Subtotal:				\$4,719.16		
Grand Total:				\$4,719.16		

Michael Woods (Brinkley Sargent Wiginton Architects)

5000 Quorum Drive, Suite 600 Dallas Texas 75254

Collin County

4600 Community Avenue McKinney Texas 75071

Ratcliff Constructors, LP

4200 Beltway Drive Addison Texas 75001

4-5-2024 DATE

SIGNATURE DATE

SIGNATURE

Daum Plumbing Co. Inc

972-241-7000 Fax 972-241-7074 TSBPE 512-458-2145 S Daum#M14182 11695 Airway Blvd Roanoke, TX 76262

Ratcliff Construction LP 14901 Quorum Drive #715 Dallas, TX 75254 972-432-9969 972-432-9943 Fax	

CHANGE ORDER

Date	Estimate #		
4/2/2024	10445		

Project

22121 - Ratcliff - Co...

	-		
Description	Qty		Total
Rework Gas to 2 - HVAC Boiler for Individual Regulators		1	1,171.50
4 - 2 x 1 1/4 Reg			
4 - 2 x Close Nipples			
4 - 1 1/4 x 6 Nipples			
4 - 1 1/4 x 3 Nipple			
Labor 6 Hours			
Labor - 900.00			
Materials - 165.00			
POH 106.50			
Rework Gas to Water Heaters for Individual Regulators		1	1,380.22
2 - 1" Regulators			
2 - 1 1/2 x 1 Bell Reducer			
2 - 1 1/2 x Close Nipples		1	
2 - 1 x 8 Nipples			
2 - 1 x 6 Nipples			
2 - 1 x 4 Nipples			
Labor 6 Hours			
Labor - 900.00			
Materials - 354.75			
POH 125.48			
Collin County Detention Center	Total		
Phase I Addition	Total		

Daum Plumbing Co. Inc

972-241-7000 Fax 972-241-7074 TSBPE 512-458-2145 S Daum#M14182 11695 Airway Blvd Roanoke, TX 76262

Name / Address	
Ratcliff Construction LP	CONTROL OF THE PROPERTY OF THE
14901 Quorum Drive #715	
Dallas, TX 75254	
972-432-9969	
972-432-9943 Fax	

CHANGE ORDER

Date	Estimate #		
4/2/2024	10445		

Chris Perry, Jr.

From: Jason Mansur < JMansur@md-eng.com>

Sent: Thursday, April 4, 2024 9:58 AM

To: Brad Harris; Michael Woods; Michael Smith; mdengca

Cc: Bill Burke; BSW Tracy Wilson; Chris Perry, Jr.; Shane Worley; Jason Crawford

Subject: RE: CCADF - Regulators/Solenoid PCO

The solenoid can be connected to LC-59. That is how we would normally circuit it. We would add it to the mixing valve and recirc pump.

Jason Mansur | MD Engineering
Texas Registered Engineering Firm F-7489
1255 W 15th Street, Suite 300
Plano, Texas 75075

469.284.9678 Direct 469.467.0200 Office 469.467.0300 Fax 469.576.6518 Cell

www.md-eng.com

This message, including any attachments, contains confidential information intended for a specific individual and purpose, and is protected by law. If you are not the intended recipient, you should delete this message. Any disclosure, copying, or distribution of this message, or the taking of any action based on it, is strictly prohibited.

From: Brad Harris

Spharris@co.collin.tx.us>
Sent: Thursday, April 4, 2024 9:24 AM

To: Michael Woods <mwoods@bsw-architects.com>; Jason Mansur <JMansur@md-eng.com>; Michael Smith <msmith@md-eng.com>; mdengca <mdengca@md-eng.com>

Cc: Bill Burke <bburke@co.collin.tx.us>; Brad Harris <bjharris@co.collin.tx.us>; BSW Tracy Wilson <twilson@bsw-architects.com>; Chris Perry, Jr. <cj.perry@ratcliffconstructors.com>; Shane Worley

<Shane.Worley@ratcliffconstructors.com>; Jason Crawford <Jason.crawford@ratcliffconstructors.com>

Subject: RE: CCADF - Regulators/Solenoid PCO

Importance: High

Michael,

Can the electrician use an existing receptacle/circuit in the Boiler Room? This device appears to have a very low power draw. See attached spec sheet.

AGS Mini Merlin – AGSCH4CO Power Supply 100-120VAC, 50-60Hz Current Consumption 3W Max

PLUMBING EQUIPMENT SCHEDULE

^{**}For Construction Administration items and questions please send all correspondance to mdengca@md-eng.com.**

	PLUMBING EQUIPMENT SCHEDULE					
ITEM	DESCRIPTION	PH	HP (A)	CIRCUIT	€B	W
8.1	BOILER	120.1	11-1	11.13	20.1	
8.2	BOILER	120.1	150		200	
8.3	BOILER	120 1	654			
8.4	BOILER	120.1	164	1000		
SPI	SUMP PUMP	120.1	1.2	1A 17		
TM	THERMOSTATE MIXING VALUE	1.001	(1)	1		
RP 3	RECIRC PUMP	1,70.1	10			
	WATER SOFTENER	120.1	27.	16	201	1
FFI	FIRE FUMP	490 1	10	HWERELER	MI TILITY TRANSFO	
JEP 1	JOCKEY PUMP	480.3		(HALJRA		
BP 1	BOOSTER PUMP	2083	5	LB 62 64 66		3.8
01.1	OIL INTERCEPTOR ALARM	120:1	d)	LA 55	15.1	2.0

PART 2 - PRODUCTS

2.1 CONDENSING GAS FIRED STORAGE WATER HEATER

COMMERCIAL GAS DOMESTIC WATER HEATER 22 34 36 - 3

R. For units exceeding 200,000 BTU per hour or nominal water capacity exceeding 120 gallons, A CO detector with manual reset must be interlocked to the burner controls of the unit and monitored by the fire control panel.

- 1. The carbon monoxide detector and boilers shall be interlocked to disable the burners when the measured level of CO rises above 50ppm.
- 2. The CO detector shall disable the burners upon loss of power to the detector.
- 3. The CO detector shall be calibrated in accordance with the manufacturer's recommendations or every eighteen months after installation of the detector. A record of calibration shall be posted at or near the boiler or be readily accessible to an inspector.
- 4. Approved Carbon Monoxide Detector.
 - a. AGS Mini Merlin AGSCH4CO

This PCO response is critical for the boiler inspection.

Thanks.



Brad Harris | Building and Projects Coordinator Collin County Construction and Projects 4600 Community Ave. McKinney, TX 75071 (o) 972-547-5492 bjharris@co.collin.tx.us

From: Chris Perry, Jr. < ci.perry@ratcliffconstructors.com >

Sent: Wednesday, April 3, 2024 8:40 AM

To: Jason Mansur < JMansur@md-eng.com >; Michael Smith < msmith@md-eng.com >; mwoods@bsw-architects.com

Cc: Bill Burke < burke@co.collin.tx.us >; Brad Harris < biharris@co.collin.tx.us >

Subject: CCADF - Regulators/Solenoid PCO

***** WARNING: External Email. Do not click links or open attachments that are unsafe. *****

Jason,

Per our call, attached is the pricing we reviewed with the plumber. Please confirm the solenoid for the gas shut off should be in the off position. Additionally, please confirm power requirements and circuitry for the solenoid for electrical pricing. We are trying to get this PCO included in the next Owner Change Order package.

Thank you,

Christopher Perry Jr.

Project Manager | Ratcliff Constructors, L.P.



4200 Beltway Drive, Addison Tx 75001 972-432-9969 Office | 469-855-7192 Cell

cj.perry@ratcliffconstructors.com