WARNING!
01/19/2010


Cracks inside the fitting at the first ring.
01/19/2010

The sheer valve is underground, below
the bottom of the dispenser.

This is the sheer valve nut located approx 12" below the surface.
01/19/2010

FREQUENT
STOPS
01/19/2010