

LR 398
Elsbury's
Working!
James & Gary

Jon Kleinheksel

From: Gary Enna
Sent: Tuesday, May 14, 2013 7:46 AM
To: Jon Kleinheksel
Subject: FW: Emailing: DSCN0044, DSCN0043

Contacted:
Greg HUBBON
"Options"!

Jon, we are trying to start this road as soon as school is out. We would like to discuss options with you. Gary

-----Original Message-----

From: Gary Enna
Sent: Friday, May 10, 2013 9:46 AM
To: Billy Williams
Cc: Jon Kleinheksel; James Lorance
Subject: RE: Emailing: DSCN0044, DSCN0043

Jon, CR 398 rock to asphalt project requires removal and replacement of two tank car culverts and drainage on the south side of the road. One of the tank car crossroad culverts is in front the Elsbury's. They were contacted by Joe Williams asking if they would allow access through a temporary easement so we may correct the washout and properly place the new culvert. Joe was told "We ain't giving nothing and you ain't coming on our land". They added a new fence over a year ago 3 to 4 feet closer to the road and in the ditch. We did not see it sooner due to the amount of vegetation covering it. Looks like it is encompassing a lot of poison ivy and large trees. At a minimum, we would to ask them to remove the additional fencing the added which will impede runoff from flowing in the ditch. The prescriptive ROW was established with the original fence location. Would you like to discuss more with James and Joe or would you like us to send a letter asking them to remove the fence? Gary

See pic on Joe's last email.

-----Original Message-----

From: Billy Williams
Sent: Thursday, May 09, 2013 7:22 AM
To: Gary Enna
Cc: Jon Kleinheksel; James Lorance
Subject: Emailing: DSCN0044, DSCN0043

Gary, here are the photos of the Elsbury property & the double fence on cr. 398, there is approximately 3 to 4 feet between the 2 fences and about 16 to 17 feet from the center of road to the first fence.

Your message is ready to be sent with the following file or link attachments:

DSCN0044
DSCN0043