

GENERAL NOTES:

- 1. EXISTING CONTOURS ARE EXTRACTED USING DIGITAL MAPPING DATA PROVIDED BY NCTCOG TITLED e25837600a AND e25867600a, CONTOURS 2007 (ACS).
- 2. SETSBACKS: FRONT = 26'
- BACK = 237'NORTHSIDE = 5'SOUTHSIDE = 16'
- 3. WATER WILL BE SERVED BY CULLEOKA WATER SUPPLY CORPORATION. ONE METER WILL BE PROVIDED FOR ALL 10 SITE. 4. ELECTRIC WILL BE SERVED BY ONCOR.

FLOODPLAIN NOTE: This tract of land is designated to fall within ZONE X, according to the Flood Insurance Rate Map (FIRM) Map No. 48085C0315 J, dated June 2, 2009, prepared by Federal Emergency Management Agency (FEMA) for Collin County, Texas.

SURVEYOR'S CERTIFICATE

The survey shown hereon is a true representation of the property as determined by a survey made on the ground and under my personal supervision. All visible improvements are as shown. There are no visible encroachments, conflicts, or protrusions, except as shown. This survey conforms to the Texas Engineering and Land Surveying Practice Acts and Rules Concerning Practice and Licensure, as adopted by the Texas Board of Professional Engineers and Land Surveyors effective July 3, 2022. The property is subject to all easements of record.

> Hundukan David J. Surdukan R.P.L.S. No. 4613



LEGAL DESCRIPTION

Being a tract of land situated in the S.D. Terry Survey, Abstract No. 890 in Collin County, Texas and being all of a called 2.508 acre tract of land conveyed to Daniel and wife, Elizabeth Garcia as recorded in Instrument No. 2022000069791 of the Official Public Records of Collin County, Texas and being more particularly described in metes and bounds

BEGINNING in the east Right-of-Way (ROW) line of Live Oak Road at a 1/2" iron rod found for the southwest corner of the called 2.508 acre tract of land and said 1/2" iron rod found being the northwest corner of Lot 1, Block A of Gilbert Acres, an addition to Collin County, Texas as shown on the plat thereof recorded in Volume 2010, Page 332 of the Plat Records of Collin County, Texas;


THENCE N 00°03'00" W with the east ROW line of Live Oak Road a distance of 185.50' to a 1/2" iron rod found for corner and said 1/2" iron rod found also being the southwest corner of a called 2.500 acre tract of land conveyed to John Casey Crapser as recorded in Volume 5674, Page 3993 of the Official Public Records of Collin County, Texas; THENCE S 89°51'00" E a distance of 588.90' to a 1/2" iron rod with plastic cap stamped "4613" set for corner in the west line of Lot 4, Block 1 of Princeton Lakeside Estates, an addition to Collin County, Texas as shown on the plat thereof recorded in Volume 2022, Page 592 of the Plat Records of Collin County, Texas;

THENCE S 00°03'00" E with the west line of said Princeton Lakeside Estates a distance of 185.50' to a 1/2" iron rod found for the southeast corner of the called 2.508 acre tract of land, said iron rod being the northeast corner of said Lot 1, Block A of Gilbert

THENCE N 89°51'00" W with the north line of said Lot 1, Block A of Gilbert Acres a distance of 588.90' to the POINT OF BEGINNING, and containing 109,240 Square Feet or 2.508 acres of land.

COLLIN COUNTY OSSF NOTES

- □ Lot must utilize alternative type On—Site Sewage Facilities.
- The potential design paperwork submitted with the review shows 10 mobile homes (maximum of 3-bedrooms each) that will connect to a drip irrigation OSSF disposal system. Drip irrigation disposal is likely the disposal system chosen for this scenario as it allows for the absolute maximum of gpd for the lot. Based on the design submitted for review, there is no replacement area available if the proposed drainfield fails in any way and there is no alternative system that can be used (due to the lack of space) in lieu of drip irrigation in this scenario. It must be noted that in the case of system failure, either existing homes will have to be replaced with smaller homes or homes will have to be permanently removed from the property (the number of which will depend on the nature of the failure).
- Must maintain state—mandated setback of all On—Site Sewage Facility components from any/all easements and drainage areas, water distribution lines, sharp breaks and/or creeks/rivers/ponds, etc. (Per State regulations). No variances will be granted for setbacks or for OSSF reduction.
- There are no easements noted on the survey. If there are any easements on the lot, the number of homes allowed may be reduced. Discovery of any easements must be disclosed to Development Services immediately.
- There were no permitted/approved existing structures with associated OSSF(s) on lot at the time of approval. Any existing structures or OSSFs on lots must be reviewed and permitted by Collin County Development Services prior to any use.
- ☐ Tree removal and/or grading for OSSF may be required on lot.
- There are no water wells noted on this lot and no water wells are allowed without prior approval from Collin County Development Services
- □ Lot is limited to a maximum of 5,000 gallons of treated/disposed sewage each day.
- Individual site evaluation and OSSF design plan (meeting all State and County requirements) must be submitted to and approved by Collin County for lot prior to construction of any OSSF system.



VICINITY MAP NOT TO SCALE

OWNER
DANIEL & ELIZABETH GARCIA

ENGINEER LR ENGINEERING 2115 TEAKWOOD LN, SUITE 450 PLANO, TEXAS 75057 (972) 964–2161 CONCTACT: DAVID LEWIS

SURVEYOR SURDUKAN SURVEYING, INC. P.O. BOX 126 ANNA, TEXAS 75409 (972) 924—8200 FIRM NO. 10069500

INFRASTRUCTURE DEVELOPMENT PLAN 2.508 ACRES DANDRI PROPERTIES 2633 LIVE OAK ROAD PRINCETON, TEXAS S.D. TERRY SURVEY ABSTRACT NO. 890 COLLIN COUNTY, TEXAS