

Exhibits for Arturo's Auto Repair/Hernandez Salvage Application




Figure #1 – Subject Property Location (outside of Princeton/New Hope area just north of 380)




Figure #2 – Location of the Flood Plain in reference to the subject property

Exhibits for Arturo's Auto Repair/Hernandez Salvage Application




Figure #3 – Approximate distance to Big Branch Creek is 442'




Figure #4 – Contours surrounding the subject property and expected flow from property based on contours

Exhibits for Arturo's Auto Repair/Hernandez Salvage Application




Figure #5 – Expanded view of downstream watershed area




Figure #6 – Distance from ROW (centerline of the road) to the perimeter fencing is approximately 27'

Exhibits for Arturo's Auto Repair/Hernandez Salvage Application



Exhibits for Arturo's Auto Repair/Hernandez Salvage Application

