

FY 2015 Detention Center Camera and Monitor Upgrades

Camera	Camera Description	Type	Camera PN	Mount	Rating	DVR/Input	Matrix	Replace 2015	Camera Location	Voltage
1	Vehicle Sally Entry	PTZ		Wall/Pend.	Exterior	1-1	1	NO	North Side of Sally port	High
2	Transfer Vestibule	Fixed	VDN-5085	Corner	Interior	1-2	2	YES	Inside Interlock	Low
3	Vehicle Inside Sally	PTZ		Ceiling	Exterior	1-3	3	NO	Center PTZ inside Sally Port	High
4	Vehicle Exit Sally	PTZ		Wall/Pend.	Exterior	1-4	4	NO	Outside looking at South Sally doors	High
5	Transfer Inner	Fixed	VDN-5085	Wall	Interior	1-5	5	YES	Inside transfer, looking at Interlock	Low
6	Transfer Holding	Fixed	VDN-5085	Wall	Interior	1-6	6	YES	By property room, looking at transfer	Low
7	Bonds Release Out	Fixed	VDN-5085	Wall	Interior	1-7	7	YES	Camera across from Bonds door looking at slider	Low
8	Transfer Corridor	Fixed	VDN-5085	Wall	Interior	1-8	8	YES	By Bonds slider, looking toward transfer	Low
9	Bonds Release Out	Fixed	VDN-5085	Wall	Interior	1-9	9	YES	Hallway looking into Bonds	Low
10	Fast Track B0159	Fixed	VDN-5085	Ceiling	Interior	1-10	10	YES	Hallway looking back at Bonds	Low
11	Booking	PTZ	VG5-623	Ceiling	Interior	1-11	11	YES	Mounted by men's inmate RR	High
12	Bonds Release Vestibule	Fixed	VDN-5085	Ceiling	Interior	1-12	12	YES	Interlock looking into Bonds	Low
13	Admissions	Fixed	VDN-5085	Ceiling	Interior	1-13	13	YES	By holding cell 2, looking at slider	Low
14	Transfer Holding 8	Fixed	VDN-5085	Ceiling	Interior	1-14	14	YES	Inside Cell 8	Low
15	Staff Dining	PTZ	VG5-623	Flush	Interior	1-15	15	YES	West side of staff dining area	Low
16	Handicap Visitation	PTZ	VG5-623	Wall	Interior	1-16	16	YES	Mounted by slider looking at visitation	High
17	Bonds Release Exit	Fixed	VDN-5085	Wall	Interior	2-1	17	YES	Downstairs by elevator looking towards Bonds	Low
18	Sally North Entry	Fixed	VDN-5085	Wall	Exterior	2-2	18	YES	South side of Sally looking North	Low
19	Parking Garage	PTZ	VG5-624-ECS	Ceiling	Exterior	2-3	19	YES	Mounted outside of car wash	High
20	Transfer Holding 7	Fixed	VDN-5085	Ceiling	Interior	2-4	20	YES	Inside holding Cell 7	Low
21	Transfer Holding 6	Fixed	VDN-5085	Ceiling	Interior	2-5	21	YES	Inside holding Cell 8	Low
22	Library Entry	Fixed	VDN-5085	Wall	Interior	2-6	22	YES	In the hallway, looking at entry door	Low
23	Staff Dining	Fixed	VDN-5085	Ceiling	Interior	2-7	23	YES	Looks at slider on staff dining side	Low
24	Sheriff's Lobby	Fixed	VDN-5085	Ceiling	Interior	2-8	24	YES	Looks at Front entry doors	Low
25	Loading Deck	PTZ		Wall/Pend.	Exterior	2-9	25	NO	North end Dock of Jail	High
26	Outer Dock Vestibule	Fixed	VDN-5085	Wall	Exterior	2-10	26	YES	Looks at entrance slider on Dock	Low
27	Camera 27/CLU 5	PTZ	VG5-624-ECS	Wall w/ Arm	Exterior	2-11	27	YES	Mounted on CLU 5 looking at Generator	High
28	Kitchen/Laundry Entry	Fixed	VDN-5085	Wall	Interior	2-12	28	YES	In hallway, looking at both doors	Low
29	Medical North	Fixed	VDN-5085	Ceiling	Interior	2-13	29	YES	Looks back to the South	Low
30	SPARE					2-14	30			
31	Pharmacy	Fixed	VDN-5085	Ceiling	Interior	2-15	31	YES	In Breakroom, looks down hallway	Low
32	Medical South	Fixed	VDN-5085	Ceiling	Interior	2-16	32	YES	Looks back to the North	Low
33	Medical Waiting	Fixed	VDN-5085	Ceiling	Interior	3-1	33	YES	Mounted West side of waiting area	Low
34	SPARE					3-2	34			
35	Staff Entry	Fixed	VDN-5085	Wall	Interior	3-3	35	YES	Inside stairwell, look at entry door	Low
36	Staff Dining Inner	Fixed	VDN-5085	Wall	Interior	3-4	36	YES	Hallway looking back at slider	Low
37	Handicap C/V	Fixed	VDN-5085	Wall	Interior	3-5	37	YES	Inside interlock by building central	Low
38	SPARE					3-6	38			
39	Sheriff's Office Desk	Fixed	VDN-5085	Ceiling	Interior	3-7	39	YES	By entry door, looking at desk	Low
40	CL3 Visit G1006	Fixed	VDN-5085	Wall	Interior	3-8	40	YES	Interlock CLU 3 visitation	Low
41	CL3 Visit Outer	Fixed	VDN-5085	Wall	Interior	3-9	41	YES	CLU 3 visitation stairwell looking at door	Low
42	CL3 Inner Vestibule	Fixed	VDN-5085	Ceiling	Interior	3-10	42	YES	CLU 3 interlock looking at outer slider	Low
43	CL3 Outer Vestibule	Fixed	VDN-5085	Ceiling	Interior	3-11	43	YES	In hallway, looking at CLU 3 outer slider	Low
44	CL1 Visit Outer	Fixed	VDN-5085	Wall	Interior	3-12	44	YES	Bottom of visitation stairwell	Low
45	CL1 Inner Vestibule	Fixed	VDN-5085	Ceiling	Interior	3-13	45	NO	Inside interlock, look at outer slider	Low
46	CL1 Outer Vestibule	Fixed	VDN-5085	Ceiling	Interior	3-14	46	YES	In hallway, looking at outer slider	Low
47	Detention Lobby Visitation	Fixed	VDN-5085	Ceiling	Interior	3-15	47	YES	By help booth looking at visitors	Low
48	Detention Lobby	Fixed	VDN-5085	Ceiling	Interior	3-16	48	YES	By building central, looking at front doors	Low
49	Outside CL3	PTZ		Wall w/ Arm	Exterior	4-1	49	NO	Looking at CLU 5 Generator	High
50	Outside CL3A Electrical	Fixed	VDN-5085	Wall	Exterior	4-2	50	YES	Mounted on wall looking down	Low
51	Outside CL1	PTZ	VG5-624	Wall w/ Arm	Exterior	4-3	51	YES	Looking at CLU 3 Generator (Roof top pend.)	Low
52	SPARE					4-4	52			
53	SPARE					4-5	53			

FY 2015 Detention Center Camera and Monitor Upgrades

54	SPARE					4-6	54			
55	SPARE					4-7	55			
56	Outside CL1 A	Fixed	VDN-5085	Wall	Exterior	4-8	56	YES	Mounted on wall looking a 1A Elec.	Low
57	Outside CL3	PTZ	VG5-624	Wall w/ Arm	Exterior	4-9	57	YES	Looking at CLU 1 Generator (Roof top pend.)	Low
58	Heli Pad	PTZ	VG5-624-ECS	Wall w/ Arm	Exterior	4-10	58	YES	Mounted on CLU 1 looking at helipad	High
59	SPARE					4-11	59			
60	SPARE					4-12	60			
61	SPARE					4-13	61			
62	CL1 Visit H1006	Fixed	VDN-5085	Wall	Interior	4-14	62	YES	Inside interlock, CLU 1 visitation	Low
63	Library	Fixed	VDN-5085	Ceiling	Interior	4-15	63	YES	Looks at officer's desk	Low
64	Inner Dock Vestibule	Fixed	VDN-5085	Ceiling	Interior	4-16	63	YES	By LT office, looking at back door	Low
65	Kitchen	Fixed	VDN-5085	Ceiling	Interior	5-1	65	YES	By cart storage, looking at serving line	Low
66	Kitchen Entry	Fixed	VDN-5085	Ceiling	Interior	5-2	66	YES	Front of office, looking at entry door	Low
67	Kitchen	Fixed	VDN-5085	Ceiling	Interior	5-3	67	YES	By thaw unit, looking at ovens	Low
68	Kitchen	Fixed	VDN-5085	Ceiling	Interior	5-4	68	YES	North side of office looking at coolers	Low
69	Laundry	Fixed	VDN-5085	Ceiling	Interior	5-5	69	YES	Over washer looking at washers	Low
70	Laundry	Fixed	VDN-5085	Ceiling	Interior	5-6	70	YES	By office, looking at washers	Low
71	Kitchen Back Hall	Fixed	VDN-5085	Ceiling	Interior	5-7	71	YES	Looks at inside of back door	Low
72	Library	Fixed	VDN-5085	Ceiling	Interior	5-8	72	YES	Looks at open area mounted by officer's desk	Low
73	Admissions Holding	Fixed	VDN-5085	Ceiling	Interior	5-9	73	YES	In middle of Admissions, looking at Holding	Low
74	SPARE					5-10	74			
75	North Cluster Pit	Fixed	VDN-5085	Wall	Interior	5-11	75	YES		Low
76	South Cluster Pit	Fixed	VDN-5085	Wall	Interior	5-12	76	YES		Low
77	Employee Parking	PTZ	VG5-624-ECS	Wall w/ Arm	Exterior	5-13	77	YES	Mounted on A Mech. wall (Roof top pend.)	High
78	SPARE					5-14	78		Changed to Camera 100	
79	Sheriff's Office Parking	PTZ	VG5-624-ECS	Wall w/ Arm	Exterior	5-15	79	YES	Mounted on B Mech. wall (Roof top pend.)	High
80	SPARE					5-16	80		Changed to Camera 99	
81	CL5 Inner Vestibule	Fixed	VDN-5085	Wall	Interior	6-1	81	YES	Inside CLU 5 interlock	Low
82	SPARE					6-2	82			
83	SPARE					6-3	83			
84	SPARE					6-4	84			
85	CL5 Inner Visitation	Fixed	VDN-5085	Ceiling	Interior	6-5	85	YES	Inside CLU 5 visitation interlock	Low
86	SPARE					6-6	86			
87	SPARE					6-7	87			
88	SPARE					6-8	88			
89	SPARE					6-9	89			
90	SPARE					6-10	90			
91	SPARE					6-11	91			
92	SPARE					6-12	92			
93	CL5 Outer Visitation	Fixed	VDN-5085	Wall	Interior	6-13	93	YES	CLU 5 visitation stairwell looking at door	Low
94	Staff Entry	Fixed	VDN-5085	Wall	Exterior	6-14	94	YES	Mounted outside, looking at who is coming in	Low
95	Book In	Fixed			Interior	6-15	95	NO	In hallway, looking at Holding cell area	Low
96	Holding 3	Fixed			Interior	6-16	96	NO		
97	Holding Vestibule	Fixed			Interior		97	NO	In vestibule, looking at Holding cells	Low
98	Holding 5	Fixed	VDN-5085	Ceiling	Interior		98	YES		
99	CL5 Outer Vestibule	Fixed	VDN-5085	Ceiling	Interior	5-16	99	YES	In CLU 5 hallway, looking at interlock	Low
100	Staff Parking	Fixed PTZ	VDN-5085 VG5-624-ECS	Wall w/ Arm- ROOF	Exterior	5-14	100	YES	Mounted on C Mech. wall (Roof top pend.)	High
101	Kitchen Rear	PTZ	VG5-623-CTS		Interior		101	NO	New	
102	Traffic Cop	PTZ	VG5-623-CTS		Interior		102	NO	New	
103	Main Corridor C1400	PTZ	VG5-623-CTS		Interior		103	NO	New	
104	SPARE						104			
105	SPARE						105			

FY 2015 Detention Center Camera and Monitor Upgrades

106	SPARE					106		
107	SPARE					107		
108	SPARE					108		
109	SPARE					109		
110	SPARE					110		
111	SPARE					111		
112	SPARE					112		
113	CL1 A SEG	PTZ		Interior		113	NO	
114	CL1 A SEP	PTZ		Interior		114	NO	
115	CL1 POD B	PTZ		Interior		115	NO	
116	CL1 POD C	PTZ		Interior		116	NO	
117	CL1 POD D	PTZ		Interior		117	NO	
118	CL3 POD A	PTZ		Interior		118	NO	
119	CL3 POD B	PTZ		Interior		119	NO	
120	CL3 POD C	PTZ		Interior		120	NO	
121	CL3 POD D	PTZ		Interior		121	NO	
122	CL5 SEG	PTZ		Interior		122	NO	
123	CL5 SEP	PTZ		Interior		123	NO	
124	CL5 POD B	PTZ		Interior		124	NO	
125	CL5 POD C	PTZ		Interior		125	NO	
126	CL5 POD D	PTZ		Interior		126	NO	
127	Medical	PTZ	Ceiling	Interior		127	NO	By officer's desk
128	SPARE					128		
129	SPARE					129		
130	SPARE					130		
131	SPARE					131		
132	SPARE					132		