## EQUIPMENT SERVICES VEHICLE EVALUATION AND INSPECTION

REV 3/14/23											
UNIT#	YEAR MODEL		MAKE		MOI	EL	COLOR	DESCRIPTIO	N (2DR,MIDSIZE, ETC)		
55569	2016	Tiger			me 929	13	Yellow	Boom	Mower		
VIN: 7	783	MK	9243			TAG:		MILEAGE/H	rs —		
DEPARTME	ENT/PROPOSED	USE: L	<u> </u>		•		· 				
INSPECTION POINTS:  CONDITION											
ENGINE	<u> </u>	-	GOOD	OK.	POOR	Γ		REMA	RKS		
WIRES			3002								
HOSES	<del>**</del>		-			1	<del></del>		<del></del>		
BELTS			, 5		_	1					
EMMISSIO	N SYSTEM										
ENGINE AN	IALYSIS	_						·			
						•					
ELECTRICA			GOOD	OK	POOR	<b></b>		REMA	RKS		
BATTERY 8 GENERATO						<del>                                     </del>					
ALTERNAT				$-\sqrt{-}$		<del> </del>					
	CKS,WINDOWS	SEATS									
LIGHTING		JOLAIO		/		<del> </del>					
				<u> </u>	L			-			
EXHAUST			GOOD	ОК	POOR			REMA	IRKS		
MUFFLER				8 1							
CATALYTIC	CONVERTER'H	ANGERS									
HANGERS									<u> </u>		
PIPES				,					<u> </u>		
	& SUSPENSION		GOOD	ок	POOR	<u> </u>		REMA	ARKS		
	HT-SPRINGS		-		<b>.</b>	<del> </del>					
IDLER ARM				+	<u> </u>	<u> </u>					
A-FRAME I				$+ \times$	_	+					
SHOCKS/STRUTS TIRES-WEAR PERCENTAGE		:				<del> </del>					
AIR CONDI			-		<u> </u>						
	i		<u> </u>		-	<del>-\</del>					
BRAKES		-	GOOD	ОК	POOR			REMA	ARKS		
WEAR PER	CENTAGE										
LEAKAGE					<u> </u>		-				
INTERIOR			GOOD	- OK	POOR	<del> </del>		REMA	AKKS		
SEAT COVE			-	· /	<del> </del> -	<del> </del>		<del></del>			
SEAT BELT			ļ	+		<del> </del>					
HEADLINE CARPET	K	)		+X		<del> </del>		<del></del>			
	DOOR HANDLE			<del>                                     </del>	<del></del>	+			-		
GAUGES	, DOWNIAMOL	<del>-</del>	<del>                                     </del>	<del>                                     </del>	<del>                                     </del>	<del>                                     </del>					
,	٥.					<u> </u>					
EXTERIOR	,		GOOD	ОК	POOR	Ī			ARKS		
BODY CON						N	reds b	lades &	- skids		
PAINT		1.					_		<u>-</u>		
GLASS									<del> </del>		
APPROVED BY: DATE: 8/1/23  APPROVED BY: DATE: 8/1/33											
APPROVED BY: JOY SULL DATE: 8/1/33											
		PLEE ICOC	INA I OR וועאי				,				

**EQUIPMENT SERVICES VEHICLE EVALUATION AND INSPECTION** REV 3/14/23 UNIT# YEAR MODEL MODEL DESCRIPTION (2DR,MIDSIZE, ETC) MAKE COLOR Deere 2016 John 55568 6130M Tractor LOG 130 MPG 4863097 MILEAGE/HRS 6467 TAG: **DEPARTMENT/PROPOSED USE: INSPECTION POINTS:** CONDITION ENGINE GOOD POOR REMARKS WIRES HOSES BELTS EMMISSION SYSTEM ENGINE ANALYSIS ELECTRICAL GOOD POOR REMARKS ОК **BATTERY & CABLES** Need **GENERATOR** ALTERNATOR POWER LOCKS, WINDOWS, SEATS LIGHTING SYSTEMS POOR REMARKS **EXHAUST** GOOD ОК MUFFLER 1/ CATALYTIC CONVERTER'HANGERS HANGERS PIPES POOR REMARKS STEERING & SUSPENSION GOOD ОК 1 RIDE HEIGHT-SPRINGS IDLER ARMS A-FRAME BUSHINGS \_ SHOCKS/STRUTS 20% rengining TIRES-WEAR PERCENTAGE AIR CONDITIONER POOR REMARKS BRAKES GOOD ОК **WEAR PERCENTAGE** LEAKAGE REMARKS INTERIOR GOOD ОК POOR SEAT COVERS SEAT BELTS HEADLINER CARPET WINDOW, DOOR HANDLES

EXTERIOR	GOOD	ОК	POOR	REMARKS		
BODY CONDITION						
PAINT	1) 0.1				has some point fude / Chips	
GLASS		V				
•					- / /	

APPROVED BY: James Soul

GAUGES

DATE: 8/1/03